



工事名 もみじが丘アパート2号棟長寿命化工事

	【外壁改修】 外壁の塗替え → 耐久性の向上	【外壁改修】 外壁の塗替え → 耐久性の向上	【外壁改修】 外壁の塗替え → 耐久性の向上
工 事 実 施 前			
工 事 実 施 後			


工事名 もみじが丘アパート2号棟長寿命化工事

	【外壁改修】 外壁の塗替え → 耐久性の向上	【外壁改修】 外壁の塗替え → 耐久性の向上	【外壁改修】 外壁の塗替え → 耐久性の向上
工事実施前			
工事実施後			

工事名 もみじが丘アパート2号棟長寿命化工事

	【防水改修】 屋上防水の塗替え → 耐久性の向上	【防水改修】 屋上防水の塗替え → 耐久性の向上	【防水改修】 屋上防水の塗替え → 耐久性の向上
工事実施前			
工事実施後			

工事名 もみじが丘アパート2号棟長寿命化工事

	【塗装改修】 鉄部の塗替え → 耐久性の向上	【塗装改修】 配管の塗替え → 耐久性の向上	【塗装改修】 格子の塗替え → 耐久性の向上
工 事 実 施 前			
工 事 実 施 後			

工事名 もみじが丘アパート2号棟長寿命化工事

	【塗装改修】 玄関扉の塗替え → 耐久性の向上	【防水改修】 防水の塗替え → 耐久性の向上	【塗装改修】 配管の塗替え → 耐久性の向上
工事実施前	 A photograph of the entrance door area before the renovation. The door is a faded pink color. A sign in the foreground reads '着工前 2-7-2' (Before work starts 2-7-2).	 A photograph of the balcony floor before waterproofing. The floor is old and stained. A sign in the foreground reads '防水改修工事 バルコニー防水 層間プライマー' (Waterproofing renovation work Balcony waterproofing Inter-layer primer).	 A photograph of a hallway with pipes before repainting. The pipes are old and discolored. A sign in the foreground reads '着工前 2-7-2' (Before work starts 2-7-2).
工事実施後	 A photograph of the entrance door area after the renovation. The door is now a bright, fresh pink color. A new orange safety fence is in the foreground.	 A photograph of the balcony floor after waterproofing. The floor is now a smooth, light blue color.	 A photograph of the hallway with pipes after repainting. The pipes are now a clean, bright white color.