

工事名 ひばりアパート1号棟他長寿命化工事

	【外壁改修】 外壁の塗替え → 耐久性の向上	【外壁改修】 外壁の塗替え → 耐久性の向上	【外壁改修】 外壁の塗替え → 耐久性の向上
工事実施前	 A photograph of the apartment building before renovation, showing a white facade with some signs of wear and discoloration.	 A photograph of the apartment building before renovation, showing a white facade with some signs of wear and discoloration.	 A photograph of the apartment building before renovation, showing a white facade with some signs of wear and discoloration.
工事実施後	 A photograph of the apartment building after renovation, showing a clean, bright white facade.	 A photograph of the apartment building after renovation, showing a clean, bright white facade.	 A photograph of the apartment building after renovation, showing a clean, bright white facade.

工事名 ひばりアパート1号棟他長寿命化工事

	【外壁改修】 外壁の塗替え → 耐久性の向上	【外壁改修】 外壁の塗替え → 耐久性の向上	【屋根改修】 屋根防水の改修 → 耐久性の向上
工事実施前			
工事実施後			